Initial	Date
<u>cw</u>	4-18-96
19	4/18/94
	And the second s
A SECTION AND ADDRESS OF THE PROPERTY OF THE P	Charles and the same of the same

BA WTR WR ND Mail Stop 60189

APR 1 8 1996

Memorandum

To:

GARD, North Dakota/South Dakota

Attn: Ron Shupe

From:

Chief, Division of Water Resources, Region 6

Subject: 1995-1996 Annual Water Use Report/Management Plan

The subject reports for Tewaukon, Lake Elsie, and Storm Lake National Wildlife Refuges have been reviewed and approved as submitted.

Please extend our thanks to Refuge personnel for the timely submission of the reports.

/S/ CHERYL C. WILLISS

bcc: WR rf

RO rf

WTR:LCoe:lc:3/11/96 w:\wateruse\tewaukn.96



United States Department of the Interior

FISH AND WILDLIFE SERVICE

Tewaukon National Wildlife Refuge Complex 9754 1431/2 Ave SE Cayuga, ND 58013-9764

MEMORANDUM

February 26, 1996

To:

R&W, ND Refuge/Fisheries Supervisor (60130)

Denver, CO

From:

Refuge Manager, Tewaukon NWR Complex (62660)

Cayuga, ND

Subject: 1996 Annual Water Management Plan and 1995 Use Report

List of Water Rights

Declaration of Filing dated September 1, 1934, for Lake Tewaukon and East and West White Lake (including Cutler Marsh), 7,198 acre-feet storage, 4,251 acre-feet seasonal from Wild Rice River.

Declaration of Filing dated September 1, 1934 claimed 397 acrefeet storage and 312 acre-feet seasonal use for Clouds Lake (Pool 8) now called Hepi Lake. Listed on the same sheet as Lake Tewaukon/White Lake, as per RO(EN) Marshall Fox's 11-14-83 memo. Water use in pools 5 through 10 is covered under this right, with Hepi Lake to be drawn down to fill these pools.

Permit #1261: 4852 acre-feet storage and 2287 acre-feet seasonal total of 7139 acre-feet. This permit covers additional storage and seasonal use in Lake Tewaukon, Cutlers Marsh and West White Lake; 409 acre-feet seasonal use to replace water to be diverted from the watershed by Sargent County Water Conservation District project; and total storage and seasonal use for Pools 3 and 4. Priority date December 28, 1964.

Tewaukon NWR #1262: 1,130 acre-feet yearly (635 acre-feet storage and 495 acre-feet seasonal use) for Sprague Lake, dated December 28, 1964, diversion from an unnamed creek in the SE1/4NW1/4, Section 2.

Tewaukon NWR #1263: 686 acre-feet yearly for Mann Lake (236 acre-feet) and Horseshoe Slough (450 acre-feet) dated December 28, 1964, diversion from the Wild Rice River.

Tewaukon NWR #3816 Nickeson Tract: 571 acre-feet (474 acre-feet storage, 97 acre-feet annual use) for the Nickeson Bottoms, a tract jointly owned by the ND Game and Fish Department, US Bureau of Reclamation and USFWS. Diversion is from the Wild Rice River, W 1/2 Section 27, T. 130 N., LTL, R. 54 W. Priority date August 15, 1985.

2. <u>Water Use - 1995</u>

The Wild Rice River, LaBelle Creek, Frenier Dam Outlet and Sprague Lake Creek flowed well above average this year, exceeding management levels in all wetlands. The Wild Rice River continued a steady flow the entire year. It is believed that the cleaning of the Crete-Cogswell drain in 1984-85 plus average snow caused this increased flow in the Wild Rice River. Most wetlands on the Refuge were filled by the above normal runoff, and they held water into freeze-up.

Pool 1 (Lake Tewaukon): The lake was frozen at 1148.30 (1148.0 is full pool. Inflow began on March 12, and rapid runoff from LaBelle Creek caused the spillway at the east end of Lake Tewaukon to be overtopped by about 1 foot. On March 17, outflow peaked at 1150.63 and a full pool was maintained.

Parker Bay (east end of Lake Tewaukon): Inflow from LaBelle Creek flowed into Parker's Bay and raised the water level to about 6 feet. The high water from LaBelle Creed over-topped the East Dike of Lake Tewaukon.

Pool 2 (Cutler Marsh): This pool filled rapidly due to flooding received runoff from the Wild Rice River and West White Lake. It reached 1152.48 on March 16, 1995. Additional stoplogs were removed on August 10 for carp management purposes. At freeze-up the level of this pool was 1148.50.

Pool 2A: Pool 2a was kept as dry as possible in order to repair the dike.

Pool 3 (Maka Pool): Pool 3 peaked at 1156.01 on March 15. We attempted to hold this pool at 1155.0. At freeze-up the level of this pool was 1154.0.

Pool 3A: This pool is filled to the same level as Pool 3 and remained that way all year.

Pool 4 (River Pool): This pool remained about the same level the entire year peaking at 1161.11 on March 13. Maintained an operating level of 1160 until freeze up at 1160.03.

Pools 5, 5A, 6, 7, 7A: All pools started dry but rapidly filled during the rapid runoff. High water washed out Pool 5 water control structure, and it was therefore dry. All remaining pools were full throughout the year.

Pool 8 (Hepi Lake): A maximum depth of 7 feet was reached on March 13, and the desired management level of about 2.5 feet was obtained. Freeze-up was at 6.0 feet deep.

Pool 9: Natural run-off filled this pool to a level of approximately 6 feet deep.

Pool 10: This pool was over-topped and reached a depth of approximately 8 feet in March. Draw-down operation lowered the pool to 6 feet by August 1.

Pool 11 (West White Lake): Again this year this unit was full and peaked at 1151.15 on August 14. Freeze-up was at 1149.40.

Pool 12 (East White Lake): Waterfowl loafing and brood use were excellent this year, however, average snowfall and pumping from Pool 11 caused us to have 9 feet of water at freeze-up.

Pool 13 (Mann Lake): This pool contained 5 to 7 feet of water at freeze-up. Natural run-off prevented us from lowering this pool to achieve maximum duck use.

Pool 14 (Sprague Lake): Reached maximum depth at freeze-up. 11.86 on March 13. Reached operating level of 8/9 feet on March 21.

Pool 16 (Horseshoe Slough Group): Thanks to the average snowfall, local runoff filled this group of 8 wetlands (244 wet acres) completely. All pools provided excellent waterfowl habitat.

3. <u>Impoundment Data</u>

Please see the attached chart for capacities for each pool at various elevations. No formal inflow/outflow records were maintained. Please see Section #2 above for elevation changes for the various pools.

4. 1996 Plans

Pool 1 (Lake Tewaukon): Maintain 1148.0 MSL. This elevation will help to maintain the sport fishery habitat.

Parker Bay (east end of Lake Tewaukon): If possible, lower to maintain a 2½-3 foot depth for waterfowl production.

- Pool 2 (Cutler Marsh): Try and maintain the pool at 1152.0 MSL to flood dense cattails in the west end without killing vegetation in the lower end. Small amounts of water will be released in May-August to help facilitate shorebird use.
- Pool 3 (Maka Pool): Maintain pool at 1154.5 and stabilize as quickly as possible before over-water duck nesting is initiated. If needed, supply water to Pools 2A and 3A. Try an establish a cattail fringe on the cross dike.
- Nickeson Bottoms: Cattails have been brought under control, however must try and lower this pool from approximately 6 feet to a depth of 3 feet.
- Pool 4 (River Pool): Maintain approximately 1160 MSL for duck nesting, especially over-water nesting, and stabilize as quick as possible before April 15. Maintain muskrat populations by keeping this pool at this elevation.
- Pools 2A, 3A, 5A, 6, 7, 7A: If possible, fill to maximum depth to flood cattails. The pools will dry out rapidly through an average summer due to evaporation. NAWCC funds will be used to repair pool 5 dike.
- Pool 8 (Hepi Lake): Initially 5-6 feet of water may be needed to supply Pools 7A, 7, 6, 5A, 5, 3A, and 2A downstream. Hepi Lake will be drawn down in late summer to repair north outlet using NAWCC funds.
- Pool 9: Will receive water from Hepi Lake during construction.
- Pool 10: Lower to a depth of 2½ feet. It should be allowed to go dry by late August to maintain its highest use as a semi-permanent wetland.
- Pool 11 (West White Lake): Maintain depth at $4-4\frac{1}{2}$ feet to slow cattail invasion. If necessary pump water to Pool 12 to keep from flooding County Road 5.
- Pool 12 (East White Lake): Add no water to this pool unless there is a need to pump water from Pool 11 to protect County Road #5 Allow gradual drying to reestablish cattails.
- Pool 13 (Mann Lake): Add no water to this pool at 4-6 feet deep. We are above optimum operating level.
- Pool 14 (Sprague Lake): Maintain maximum pool, about 8½ to 9 feet in order to maintain the sport fishery.

Pool 16 (Horseshoe Slough): Gravity flow water from the Wild Rice River to fill all pools. Pool A will be lowered to repair Banish "J" dike.

5. Location Map

Please see Section #2 for the revised Refuge Map on which all management pools are marked.

Fred G. Lieve

Fred G. Giese

Attachments

	NAL WILDLIFE REFUGE ations and Acres	
Pool 1 - Tewaukon	1149	1015
- Parker's Bay	1149	95
Pool 2 - Cutler's Marsh	1152	246
Pool 2A		30
Pool 3 - Maka Pool	1156	125
Pool 3A	•	18
Pool 4 - River Pool	1159	108
Pool 5	1160	6
Pool 5A		5
Pool 6	1165	6
Pool 7	1178	21
Pool 7A		106
Pool 8 - Hepi Lake	1179	106
Pool 9	1167	10
Pool 10	1173	5.5
Pool 11 - W. White Lake	1151	80
Pool 12 - E. White Lake	1147	103
Pool 13 - Mann Lake	1207	57
Pool 14 - Sprague Lake	1209	186
Pool 16 - Horseshoe Slough Pool 1 Pool 2 Pool 3 Pool 4 Pool 5 Pool 6 Pool 7	1210 1206 1206 1206 1206 1206 1206	244 119.7 42.5 10.3 30.3+ 24.5 2.8+ 14.5

WATER USE REPORT/ MANAGEMENT PLAN SHORT FORM

Lake Elsie NWR, Richland County Station Name	Summer, 1995 (date not recorded) Date Of Inspection
Declaration of Filing: 8/30/37 Water Right No. Several (522 acre-feet storage) (900 acre-feet seasonal) Water Diverted: Yes No_X	Considerable local runoff, at least Source(s) two drainage ditches springs Means of Diversion None Rate
*Impoundment(s): Yes No_X_	Rate
*Well(s): Free Flowing none-known gpm Pumped gpm	Type of Use: Surface Irrigation (Crop) Fish & Wildlife XX Stock Domestic Other high public use: swimming water skiing, fishing
Over Climatic Conditions:	
Condition of Facilities: No facilities proposed Water Program: None, no water maximum the lake spills north through a (da	111 MAN - 1895 1111
Comments: The lake is an extremal	culvert.
Comments: The lake is an extremely popul Richland County Commissioners, Richland Count Game and Fish are looking at a project that vocunty road, provide a fishing bridge, but possibility of a walleye rearing pond.	ar summer recreational area. The Y Wildlife Club and the North Dakota Would include raising the bridge and ild a carp trapping area and the

Fred G. Giese, Refuge Manager Date

^{*}If more than one impoundment or well, please attach additional sheet.

WATER USE REPORT/ MANAGEMENT PLAN SHORT FORM

Storm Lake NWR, Sargent County	Summer, 1995	
Station Name	Date Of Inspection	
Declaration of Filing: 8/30/37	Drainage ditch (legal)	
Water Right No.	Source(s)	
Several		
(522 acre-feet storage)	Means of Diversion <u>Uncontrolled</u>	
(900 acre-feet seasonal)	Rate <u>Unknown</u>	
Water Diverted: Yes No_X_		
	Water Level <u>est 654 acre-feet</u>	
	(Elevation or Est. Storage Amount)	
*Impoundment(s): Yes No_X_		
	Type of Use:	
	Surface Irrigation	
*Well(s):	(Crop)	
Free Flowing none gpm	Fish & Wildlife X Virtually no	
Pumpedgpm	Stockpublic use	
	Domestic	
	Other	

Over Climatic Conditions:

Condition of Facilities: A diversion dam at the head of the feed ditch serving Storm Lake washed out well before 1976. Apparently someone decided it wasn't worth repairing.

Proposed Water Program: No water management capability is present. Water runs down the ditch into the lake to an unknown degree each spring. Water did fill Storm Lake in 1993.

Comments: The lake serves as an excellent waterfowl loafing sanctuary with good use by snow geese, canvasbacks, redheads, lesser scaup, and tundra swans. Water levels fluctuate on their own. If active management was initiated, some degree of improvement might be gained by a cycle of drawdown management. It is questionable if the benefits would be worth the costs for Storm Lake alone. However, when you look at the other three wetlands to the south we should continue to work with Ducks Unlimited and put the Mini Joint Venture back on tract. The Golf Course Association of Milnor has been very quiet in their request to use lake water to irrigate portions of the Storm Lake Golf course. The Association was granted a conditional water right, junior to that of the FWS. The Golf Course Association is now looking into doing some new landscaping and has contacted us about the possibility of doing some cosmetic changes on the feeder ditch.

Fred G. Giese, Refuge Manager Date

^{*}If more than one impoundment or well, please attach additional sheet.